

Indiana 811 Positive Response Codes

Code	Current Description
1	Marked – Does conflict, underground facilities have been marked.
1A	Marked with Exceptions - High Profile Utility – High profile utility in conflict; utility owner will attempt to contact you to schedule surveillance.
1B	Marked with Exceptions - High Priority Subsurface – High priority subsurface installation in conflict. Excavator MUST notify the member of the excavation or demolition start date and time.
2	Clear – No underground facilities are in the area where the excavation will take place.
3A	Unmarked - Could Not Gain Access to Property – Locate technician could not gain access to property; call Indiana 811 to schedule access.
3B	Unmarked – Incorrect Address Information - Incorrect address information. Call Indiana 811 to verify the information on the ticket.
3C	Unmarked - Marking Delay Requested with Excavator – Marking delay requested. Excavation site is unmarked. The locate technician cannot mark within two full working days. Per Indiana Law, the operator shall notify the excavator responsible of the operator’s determination and shall provide additional information.
3D	Unmarked - Marking Instructions are Unclear – Locate instructions are unclear. Call Indiana 811 to clarify where on the property you will be excavating and need the underground facilities located.
3E	Unmarked - Excavation Already Performed – The excavator has performed the excavation prior to the locators’ arrival.
3F	Unmarked - Line is untonable – Line is untonable and utility has been notified to resolve the issue.
4	Private Line – This is a private line and it is not the responsibility of the members of Indiana 811 to locate private facilities. For more information, please visit https://indiana811.org/myutilities .